Day Phone: 689-323-3223 VID: 5UXFA13566LY42299 Night Phone: Mileage: Fax: Estimate Ref: 1003 Date: May 19, 2025 Time: 03:25 PM Vehicle: 2005 BMW X5 (E53) L6-3.0L (M54) Description **Extended** Labor 65.00 / hr 1 Diagnose No Start Symptom: 195.00 3.00 Tested Fuel Delivery - Good Tested Ignition Delivery - Not Good Performed in-depth diagnostics troubleshooting lack of ignition. D1 - EWS Immobilizer out of sync with ECU/EMS Reprogramming EWS III module required to resync immobilizer. Customer declined further action. **Labor Total** 195.00 Parts Total 0.00 -----Sub-Total 195.00 \$ 195.00 Total

Date

Service Writer: Service Tech:

Customer:

Address: City, State:

Signature

John